

AUGUST 1, 1994



ALL HIGHFLYER OWNERS

USA Office:

Box 2042, Wintersville, Ohio 43952

Telephone: 614 264-6599 Fax: 614 266-2953

SERVICE BULLITIN:

RE: HIGHFLYER 1:

PLEASE NOTE FROM THE ENCLOSED DRAWING THAT A SMALL SURFACE CRACK WAS NOTED ON HIGHFLYER 1 (ENGLAND) AT THE TOP OF THE GUSSET LOCATED ON THE COUNTERWEIGHT ARM.

PLEASE MAKE A VISUAL INSPECTION OF YOUR HIGHFLYER.

THIS CAN EASILY BE VIEWED THRU THE HATCH LOCATED AT THE TOP OF THE TOWER.

PLEASE REPORT ANYTHING IRREGULAR TO OUR U.S. OFFICE.

IF YOU HAVE ANY FURTHER QUESTIONS, FEEL FREE TO CALL.

*Funfair Equipment, Design, Manufacture and Refurbish*



A.R.M. (U.K.) LTD.  
Unit 1, Enstone Airfield,  
Enstone, Oxford OX7 4NW, England

Telephone (0608) 677468  
Fax: (0608) 678765

Directors: M. Steffens, S. Steffens  
V.A.T. No. 348-3613-46  
Registered In England No. 1534898