

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — February 2015

387. Huss Enterprise/UFO central hub and boom cracking

Huss has issued a service bulletin detailing a crack found at the central hub of one of its Enterprise devices. The bulletin recommends that a qualified inspector assess the area depicted for any defects.

The information contained within is that of the manufacturer and not NAFLIC. When following the advice from the manufacturer, you are reminded of your duties and responsibilities under HSG175 regarding modifications.



Mailing address:
HUSS Parts & Service GmbH Postfach 110206 D-28082 Bremen

Head office:
Emil-Sommer-Straße 4-6, D-28329 Bremen
Tel. 0421-49900-0 Fax 0421-49900-56
E-mail: service@hussparts.com
Internet: <http://www.hussrides.com>

**Alton Towers
Head of maintenance**

North Staffordshire ST10 4DB

United Kingdom

Your Ref.	Our Ref.	Ext.	Date
	SER-AW	-30	12.01.2015

Service-Information 05-02

To whom it may concern:

Our records indicate that you are the owner/operator of an Enterprise/UFO amusement ride manufactured by Huss. If you are no longer in possession of this ride please return this letter with the contact data of the new owner to Huss Parts & Service GmbH.

During a general overhaul of an Enterprise ride, cracks in the area of the boom head have been detected.


A related picture and a drawing are attached to this letter.

It is strongly recommended to get this area inspected by a certified company.

Do not hesitate to get in touch with us in case of any questions or concerns.

Kind regards

HUSS Parts & Service GmbH



CENTRE LINE CRACK
L = 1600mm

