Majestic Manufacturing, Inc. • P.O. Box 128 4536 State Route 7 • New Waterford, Ohio 44445

SUBJECT: MUSIK EXPRESS FOLDING STAR

ATTN: OWNER/OPERATOR,

This Bulletin pertains to operation of your Majestic unit. This Service Bulletin must remain with owner's manual. If you have any questions regarding this Bulletin, contact our office at (330) 457-2447, M-F 8:00 a.m.-4:30 p.m. E.S.T. • Fax 457-7490

## SERVICE BULLETIN

Date:

May 1, 1996

S.B. Number:

96-3

Notice:

This service bulletin is to all Majestic Music Express units. It has come to our attention that the fasteners holding the plastic fixture to the aluminum frame of the folding star may come loose during operation of the ride. A thorough inspection of each fastener is required. If a correction is needed prior to receiving appropriate fasteners, zip ties can be used temporarily. Call our service department for appropriate fasteners to correct this problem at no charge.

This service bulletin must remain with owner's manual at all times.



SUBJECT: ELECTRICAL CONNECTION ON THE MUSIK EXPRESS

ATTN: OWNER/OPERATOR,

This Bulletin pertains to operation of your Majestic unit. This Service Bulletin *must* remain with owner's manual. If you have any questions regarding this Bulletin, contact our office at (330) 457-2447, M-F 8:00 a.m.-4:30 p.m. E.S.T. • Fax 457-7490

#### SERVICE BULLETIN

Date:

May 2, 1996

S.B. Number:

96-4

Notice:

This service bulletin is to all Majestic Music Express units. Periodic inspections is required on all main breakers and fuse connection areas. Thermal expansion and contraction of all attachment points may result in loose connection and eventually burn entire breaker or fuse holder. Inspect and verify integrity of the electrical system to factory standards.

This service bulletin must remain with owner's manual at all times.

Majestic Manufacturing, Inc. • P.O. Box 128 4536 State Route 7 • New Waterford, Ohio 44445

SUBJECT: WIND BRACE ON MUSIK EXPRESS

ATTN: OWNER/OPERATOR,

This Bulletin pertains to operation of your Majestic unit. This Service Bulletin *must* remain with owner's manual. If you have any questions regarding this Bulletin, contact our office at (330) 457-2447, M-F 8:00 a.m.-4:30 p.m. E.S.T. • Fax 457-7490

# SERVICE BULLETIN

Date:

May 3, 1996

S.B. Number:

96-5

Notice:

This bulletin is to all Majestic Musik Express units. We have been informed that several units were shipped without the capability of safety keying roof wind braces to eliminate the possibility of the brace not remaining secure while the ride is in operation. Please call the factory to discuss the procedure and resolving the situation.

This service bulletin must remain with owner's manual at all times.

Majestic Manufacturing, Inc. • P.O. Box 128 4536 State Route 7 • New Waterford, Ohio 44445

SUBJECT: GENERAL INSPECTION MUSIK EXPRESS

ATTN: OWNER/OPERATOR,

This Bulletin pertains to operation of your Majestic unit. This Service Bulletin must remain with owner's manual. If you have any questions regarding this Bulletin, contact our office at (330) 457-2447, M-F 8:00 a.m. 4:30 p.m. E.S.T. • Fax 457-7490

## SERVICE BULLETIN

Date:

May 6, 1996

S.B. Number:

96.7

Notice:

This bulletin is to inform owner/operators of the daily and periodic inspections of the following areas on the Musik Express to insure proper factory standards for a safe and efficient ride.

Listed below are the main areas to inspect:

- 1. Interior and exterior of each tub for sharp objects, loose connections or safety equipment and placard not up to factory standards.
- 2. All safety pins and R keys for wear, fatigue or missing from unit. Tubs, sweeps, center etc.
- 3. Anti skid strip on walk board for wear, looseness or missing from unit.
- 4. Safety gates working properly and effectively.
- 5. E-stop button working properly.

This service bulletin must remain with owner's manual at all times.

MAJESTIC MFG + 19413522919 02/01/01 18:08

Majestic

Majestic Manufacturing, Inc. • P.O. Box 128 4536 State Route 7 . New Waterford, Ohio 44445

POLDING MOTOR SWEEP TORQUE STIFFNER PLATE. SUBJECT:

ALL MAJESTIC MUSIK EXPRESS UNITS.

This Bulletin penalins to operation of your Majestic unit. This Service Bulletin must remain with owner's manual. If you ATTN: OWNER/OPERATOR, have any questions regarding this Bulletin, contact our office at (216) 457-2447, M-F 8:00 a.m. 4:30 p.m. E.S.T. • Fax 457-7490

# SERVICE BULLETIN

June 24, 1997 Date:

S.B. Number 97-1 Sheet 1 of 1

Notice:

This Service bulletin is to all Musik Express units. We have been informed that the two folding motor sweeps, inside bushings may experience excessive wear.

Call the factory for installation instructions of the torque plates to the folding motor sweeps. These plates P/N H-1756 are available at no charge if ordered within 90 days of this bulletin.

This Service Bulletin must remain with the owners manual at all times. All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

	Date of the pages 2	
Post-it Fax Note	7671 Gran Z. Rivelage	#
TO RIDE INSE	Phone \$ 850-912-2330	1
Co./Dept.	Phone *850-972-2330 Fax 1 850 - 413-8513	
Fax #		