Ride distributed by: Zamperia, Inc. 49 Fanny Road Boonton, NJ 07005 USA

Phone: 973.334.8133 Fax: 973.334.6880

email: zamperla@zamperlausa.com



Bulletin No: 12-MJ01

Release Date: 22 August 2012 Effective Date: 22 August 2012

Supersedes: n/a

Completion Date: 22 August 2012

Page: 1 of 2

## SERVICE BULLETIN

Mini Jet family
or to January 1 1996

## Abstract Of Issue:

There is a potential for a crack in the area of the weld of the sweep arm - fork.

Reason For Release:

Same.

Weekly perform visual inspection on the welds of the sweep arms - fork of the ride.

Annually perform a non-destructive test (NDT) by means of magnetic particle according to ASTM E709,

EN 1290 or equivalent

Notify Zamperia if a crack exists in the weld.

Detail Of Issue:

Diagram of the zone with area indicated (Page 2 of 2)

Future Action To Be Taken:

Follow this maintenance and inspection procedure in the instruction manual.

