

Issuing Entity:
Larson International Inc.
P.O. Box 638
Plainview, TX 79073-0638
U.S.A.
Phone 806-293-1353

Fax 806-293-5215 www.larsonintl.com Bulletin No.: L03-003
Release Date: 02/24/03
Effective Date: Immediately

Supercedes: N/A
Completion Date: N/A

Page: 1 of 1

SERVICE BULLETIN

Ride Manufacturer: Larson International Inc. Affected Production Dates: Al

Ride Name: Ring of Fire & Crazy Train Affected Serial Nos.: All units

Ride Manufacturer: Hi Roller Company Affected Production Dates: All Ride Name: Hi Roller & Ring of Fire Affected Serial Nos.: All units

Ride Manufacturer: LMC, Inc. Affected Production Dates: All

Ride Name: Super Loops Affected Serial Nos.: All units

Abstract Of Issue:

Clarification of rider restrictions

Reason for Release:

Larson International Inc. has learned that some operators are not following proper guidelines for rider restrictions. This Bulletin is intended to clarify those issues.

Action To Be Taken:

Larson International Inc. requires all owner/operators of the above-named rides to enforce the following rider restrictions:

- 1. Each rider is to be at least 48" tall.
- 2. No single riders are allowed. There must be 2 riders in each seat.
- 3. Patrons must be of the height, weight and shape to properly fit in the passenger seats. The restraint must properly and fully engage.
- 4. The patron must have upper body strength in order to properly sit in the seat, thighs and upper leg strength to allow the lap bar to engage and retain the patron in the seat.

Larson International Inc. issues notifications for the benefit of owners of amusement rides manufactured by Larson International, Inc. As a service to the industry, and in the interest of employee and public safety, Larson International, Inc. also issues notifications for the benefit of owners of amusement ride equipment for which the manufacturer no longer exists such as LMC, Inc. and Hi-Roller Company. In doing so, Larson International, Inc. does not assume liability for losses associated with amusement ride equipment built by manufacturers other than Larson International, Inc.