

Issuing Entity: Larson International Inc. P.O. Box 638 Plainview, TX 79073-0638 U.S.A. Phone 806-293-1353 Fax 806-293-5215 www.larsonintl.com

Bulletin No.: L16-001 Release Date: 3/16/16

Effective Date: Immediately

Supercedes: N/A Completion Date: N/A Page: 1 of 2

## SERVICE BULLETIN

Ride Manufacturer: Larson International Inc. Affected Production Dates: All

**Ride Name: FLYING SCOOTERS Affected Serial Nos.:** 14-26, 30

Install a set of normally closed contacts in the E-stop button. **Abstract Of Issue:** 

Reason for Release: A failure of the 120V power supply circuit can cause the E-stop to not

stop the ride when pressed.

**Action To Be Taken:** Install a set of normally closed contacts in the E-stop wired as

shown on page 2.

**Detail Of Issue:** 

**Revised Electrical Schematic on page 2.** 

Larson International Inc. issues notifications for the benefit of owners of amusement rides manufactured by Larson International, Inc. As a service to the industry, and in the interest of employee and public safety, Larson International, Inc. also issues notifications for the benefit of owners of amusement ride equipment for which the manufacturer no longer exists such as LMC, Inc. and Hi-Roller Company. In doing so, Larson International, Inc. does not assume liability for losses associated with amusement ride equipment built by manufacturers other than Larson International, Inc.

