



FARFABBRI S.R.L.

MANUFACTURERS OF AMUSEMENT RIDES

45032 BERGANTINO (Rovigo) Italy
Via Giovecca, 74 - Tel. 0425 / 87420 - 87142
M/710794 - C.C.I.A.A. RO N. 90591 - TRIB. RO REG. SOC. N. 4028
C. F. e P. IVA 0072400 029 4
TELEX 434839 SPARCO I - TELEFAX 0425-878113

SAFETY BULLETIN

RIDE: RANGER (KAMIKAZI, PHOENIX) DATE: SEPTEMBER 07, 1990
SUBJECT: STAR LIGHT FIXTURE BULLETIN NUMBER: F014

It has come to the attention of **FarFabbri, s.r.l.**, of instances when the starlight fixture (*) has separated from the metal frame, resulting in the fixture falling on the platform when the ride is operating. It is extremely important that these stars be immediately inspected to assure that they are attached firmly to the framework. If found that the fixture is becoming loose, please contact Exsaco Corporation, One North Santa Fe Street, Alvarado, Texas 76009, 817-783-2265, immediately for instructions as to the repair.

