

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — JUNE 2008

337.Fabbri Booster Accident in Paris, France

The committee has received some information regarding the fatal accident on a Booster ride in Paris, France.

It is understood that the failure was unlikely to have been a result of operational use. Further this failure may have been a result of accidental forces caused during the assembly and/or disassembly of the device. This appears to have resulted in a high stress low cycle fatigue failure and in an area that would not normally be expected to have had a problem in normal operation. IB's are reminded not to limit their inspections to areas that would normally be covered.

We have been unable to obtain more information at this point in time.

Committee Members:- Mr. R Nicholls(Chairman), Mr. Peter Smith,
Mr. John Green, Mr. Phil Mitchell, Mr. Ron Dale, Mr. Mark Wolstenholme, Mr. Graham Dockerty & Mr. David Inman

© June 2008

PO BOX 752, SUNDERLAND, SR3 1XX

TEL & FAX: (0191) 5239498

standards@naflic.org.uk