## Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. \* PO Box 128 4536 State Route 7, New Waterford, Ohio 44445

Subject: Musik Express Preventive Maintenance on P.C. Boards

## ATTN: OWNER/OPERATOR

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin <u>must</u> remain with the owner's manual at <u>all</u> times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m. -4:30p.m. E.S.T. \*\* Fax 330/457-7490.

## **SERVICE BULLETIN**

Date: May 6, 1996

S.B. Number: 96-6

## Notice:

General Preventative Maintenance on the main P.C. Control Board is required in order to receive the maximum benefits from this unit. Stable conditions must exist.

The P.C. board must be free from:

- 1. Excessive dust
- 2. Moisture
- 3. Heat
- 4. High/low or unregulated voltage
- 5. High/low or unregulated Hertz cycle
- 6. Loose connections
- 7. Untrained personnel

The maximum RPM required is 13.5. This speed should be maintained and not exceeded.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.