



APR 18 1991

DEPARTMENT OF LABOR
CARNIVAL & AMUSEMENT RIDE
INSPECTION DIVISION

NEW HAMPTON RIDES 7330 WEBER LAKE ROAD PORTAGE DES SIOUX, MO. 63373

Service: 314-753-2381

314-899-0955

Sales: 800-767-0171 Fax: 314-753-2004

MANDATORY PRODUCT SAFETY UPDATE RE: ROCK, SPIN & ROLL

TO WHOM IT MAY CONCERN:

IT IS ADVISED THAT ALL ROCK, SPIN & ROLL RIDES MANUFACTURED BEFORE JANUARY 1, 1979 BE TESTED AT THE BASE OF THE MAIN SHAFT OF THE VEHICLE FOR FATIGUE DUE TO EXTENSIVE USE.

THE MAIN SHAFT IS LOCATED IN THE CENTER OF THE VEHICLE. THIS SHAFT WILL HAVE 1 % " DIAMETER AND IS 31" IN LENGTH.

NDT/ULTRASOUND TESTING IS STRONGLY RECOMMENDED.

IF REPLACEMENT BECOMES NECESSARY THIS PART IS AVAILABLE AT THE FACTORY. INSTALLATION INSTRUCTIONS INCLUDED.