



FARFABBRI S.R.L.

MANUFACTURERS OF AMUSEMENT RIDES

45032 BERGANTINO (Rovigo) Italy
Via Giovecca, 74 - Tel. 0425 / 87420 - 87142

M/710794 - C.C.I.A.A. RO N. 90591 - TRIB. RO REG. SOC. N. 4028

C. F. e P. IVA 0072400 029 4

TELEX 434839 SPARCO I - TELEFAX 0425-878113

SERVICE BULLETIN

RIDE: Ranger (Kamikaze, Phoenix) DATE: 11-15-89

PRE-1990 MODELS

SUBJECT: Latch Springs in Lap bar Assembly BULLETIN NUMBER: FR020

It has been found through inspection of operating rides, that the springs used to activate lock bars and solenoids are too weak. It is therefore necessary to replace all springs immediately. These springs are available at no charge from Exsaco Corporation, One North Santa Fe St., P.O. Drawer 328, Alvarado, Texas 76009. This change must be completed within 20 days from receipt to this letter or before ride is operated for public use.

When springs are replaced, please complete the enclosed form and return to Exsaco Corporation, P.O. Drawer 328, Alvarado, Texas 76009.