MANUFACTURERS OF AMUSEMENT RIDES

45032 BERGANTINO (Rovigo) - Italy Via Giovecca, 74 - Tel. 0425/87420 - 87142 - Fax 0425/805113 M/710794 - C.C.I.A.A. RO N. 90591 - TRIB. RO REG. SOC. N. 4028 Cod. Fisc. e P. IVA 0072400 029 4

## SERVICE BULLETIN

Bulletin Number FR026

TO:

All Owners of Ranger (aka - Kamikaze, Typhoon, Hi-Flyer) Amusement

Rides

RE:

Front Seat Dividers

DATE:

October 9, 1991

It has come to the attention of FarFabbri, s.r.l., that when a patron is in the front seat by themselves and the lap bar adjacent to them is in the incorrect position (up position), it is possible for the patron to come out of the shoulder safety bar. This is prevented by the installation of a bar in the middle of the seat (see drawing). Bar must be installed immediately and confirmation of installation should be mailed to: Exsaco Corporation, P.O. Drawer 328, Alvarado, TX 76009. All materials required for installation are available, free of charge, from Exsaco Corporation. These materials may be ordered by calling 1-800-545-0667 and ordering part number 6200450.

If you should have any questions, please contact Exsaco Corporation.

FarFabbri, s.r.l.