

Ride distributed by:
Zamperla Spa
36077 Altavilla Vicentina
via Mte Grappa 15/17
ITALY
Phone: +39 0444 998400
Fax: +39 0444 573720
e.mail: zamperla@zamperla.it



Bulletin No: 2015 FAMRC 01
Release Date: Jan 1, 2015
Effective Date: Jan 1, 2015
Supersedes: n/a
Completion Date: Before 2015 Operation

Page: 1 of 1

SERVICE BULLETIN

Ride Manufacturer: A. Zamperla SpA	Affected Production Dates: All
Ride Name: Family Coaster	Affected Serial Nos.: All
Model Number: Family Coaster	

Abstract Of Issue:

The rides shall have additional maintenance requirements for the lapbars (part number 9391072028A).

Reason For Release:

Cracks have been noted on T-bars (part number 9391072028A) that have been in service for more than 15 years.

Action To Be Taken:

Incorporate into the preventive maintenance program of the ride the following:
A yearly NDT by means of liquid penetrant on all T-bars by using a dye penetrant test, according to EN 571-1/ASTM E165 standards.
These tests shall be performed by a qualified NDT inspector in accordance with Practice E543 or ASNT Recommended Practice SNT-TC-1A, or both.

Detail Of Issue:

T-bars (part number 9391072028A) shall have additional preventive maintenance requirements as listed above.

Future Action To Be Taken:

If any cracks are noted during either of the inspections, remove part from service and replace part number 9391072028A with a new part.

Note: General shop terminology for the individual T-bar restraint in this bulletin may also be referred to as a lapbar.