

WISDOM INDUSTRIES, INC



COASTER BULLETIN

DATE:

MAY 1995

RIDE:

COASTER

NOTE: Serial numbers affected are #832735 thru #832835

SUBJECT:

ATTATCHMENT BOLT FOR CAR FRAME TO AXLE BASE

PER DRAWING 9C-415

Recent inspections of bolt assembly under car seat shows wear to upper washer part #BWF751. To eliminate the possibility of car frame from separating from axles assembly, the bolt, nut, and washer must be replaced as follows:

INSTALLATION:

- Turn all electrical power off (lock out). 1.
- Block cars so they cannot move on the track. 2.
- 3. Remove axle pivot bolt from under the seat liner.
- Install new 3/4" X 4" bolt and flat washer. 4.
- The bolt comes up from under the car axle assembly through the car frame. 5. (Place flat spot on side of washer next to traction plate).
- 6. Install plasic washer over bolt.
- Install fabricated washer over bolt (1/4" key stock facing up). 7.
- Thread 3/4" castle nut onto bolt (Make sure nut seats into key stock). 8.
- 9. Tighten castle nut until snug, then loosen until slot lines up with hole in bolt. Do not tighten.
- Install 5/32" cotter pin. 10.
- Repeat steps 3-10 for all cars. 11.
- 12. Remove blocks from cars.
- 13. Apply power to system.
- Run unit without passengers. 14.
- Recheck bolts to make sure they are not binding. 15.
- Complete daily check of ride and if all is in order continue as normal. 16.

Thank you for your cooperation in this matter. If you have any questions about this bulletin, please feel free to contact us at 1-800-634-6097 or 1-970-522-7515.



